

Figure 1A






Figure 1B



Finger Cross Section With Ridge Peak Above Gap



Finger Cross Section With Ridge Valley Above Gap




Figure 2B

Figure 2A

Figure 3





Figure 4






Figure 5

Figure 6




Figure 7




Figure 8




Figure 9




Figure 10




Figure 11




Figure I2




Figure 13






Figure 14



1502

Figure 15



1502

Figure 16





Figure 17






Figure 18

Figure 19





Figure 20






Figure 21




Figure 22




Figure 23

Figure 24

